

3. Cranked Beam 41.

This components standard settings have been updated to make all welds shop welds by default. The current settings were causing confusion as many users were led into thinking that parts were not welded together.

